



| | |
|---|-----|
| a | 3mm |
| b | 2mm |

| 3M | | | | | |
|-------------|------|---|---|---|---|
| Part Number | Ribs | | | | |
| | 1 | 2 | 3 | 4 | 5 |
| 3 M 180 | ○ | | | | |
| 3 M 185 | ○ | | | | |
| 3 M 190 | ○ | | | | |
| 3 M 195 | ○ | | | | |
| 3 M 200 | ○ | | | | |
| 3 M 206 | ○ | | | | |
| 3 M 212 | ○ | | | | |
| 3 M 218 | ○ | | | | |
| 3 M 224 | ○ | | | | |
| 3 M 230 | ○ | | | | |
| 3 M 236 | ○ | | | | |
| 3 M 243 | ○ | | | | |
| 3 M 250 | ○ | | | | |
| 3 M 258 | ○ | | | | |
| 3 M 265 | ○ | | | | |
| 3 M 272 | ○ | | | | |
| 3 M 280 | ○ | | | | |
| 3 M 290 | ○ | | | | |
| 3 M 300 | ○ | | | | |
| 3 M 307 | ○ | | | | |
| 3 M 315 | ○ | | | | |
| 3 M 325 | ○ | | | | |
| 3 M 335 | ○ | | | | |
| 3 M 345 | ○ | | | | |
| 3 M 355 | ○ | | | | |
| 3 M 365 | ○ | | | | |
| 3 M 375 | ○ | | | | |
| 3 M 387 | ○ | | | | |
| 3 M 400 | ○ | | | | |
| 3 M 412 | ○ | | | | |
| 3 M 425 | ○ | | | | |
| 3 M 437 | ○ | | | | |
| 3 M 450 | ○ | | | | |
| 3 M 462 | ○ | | | | |
| 3 M 475 | ○ | | | | |
| 3 M 487 | ○ | | | | |
| 3 M 500 | ○ | | | | |
| 3 M 515 | ○ | | | | |
| 3 M 530 | ○ | | | | |
| 3 M 545 | ○ | | | | |
| 3 M 560 | ○ | | | | |
| 3 M 580 | ○ | | | | |
| 3 M 600 | ○ | | | | |
| 3 M 615 | ○ | | | | |
| 3 M 630 | ○ | | | | |
| 3 M 650 | ○ | | | | |
| 3 M 670 | ○ | | | | |
| 3 M 690 | ○ | | | | |
| 3 M 710 | ○ | | | | |
| 3 M 730 | ○ | | | | |
| 3 M 750 | ○ | | | | |